




Star delta control wiring


बिल्कुल आसान तरीके से ।





**3 Phase Motor Connection STAR/DELTA
Without Timer Control Diagram**





Control Circuit Diagram of Automatic Star Delta (Y-Δ) starter with Timer for 3-Phase Motor.

